ECS Configuration Change Request					Page 1 of Page(s)				
1. Originator	2. Log Date:	3. CCR #:		4. Rev:	5. Tel:		6. Rm #:	7. Dept.	
Robert Cole	01/30/02	02-0075			301-925-0799		2110C	SE/HW	
8. CCR Title: Swap CPUs between g0sps06 and l0sps03									
9. Originator Signature/Date			10. Class		11. Type:	1. Type: 12. Need Date: 2/8/02		: 2/8/02	
Robert Cole /s/ 1/30/02			" (CCR				
13. Office Manager Signature/Date					cu		5. Priority: (If "Emergency" III in Block 27).		
Jim Mather /s/ 1/30/02			Updat	e ECS Ba	aseline Doc.	Routine			
.			17. Schedule Impact:		18. CI(s) Af	18. CI(s) Affected:SPRHW			
19. Release Affected by this Change: 20. Date due N/A			-			. Estimated Cost: one - Under 100K			
22. Source Reference: NCR (attach) Action Item Tech Ref. GSFC Other:									
 23. Problem: (use additional Sheets if necessary) Now that S4PM is doing all of the MODIS processing, GDAAC has significantly reduced their use of PDPS. Their CPU resources on the queuing server can be better used at LDAAC. 24. Proposed Solution: (use additional sheets if necessary) Move CPU and clock boards (but not memory) as follows: 1. move 2 2x248 MHz CPU boards + clock board from g0acs04 to g0sps06 2. move 2 2x336 MHz CPU boards + clock board from g0sps06 to l0sps03 3. move 2 2x168 MHz CPU boards + clock board from l0sps03 to g0acs04 25. Alternate Solution: (use additional sheets if necessary) 									
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Inefficient allocation of computing resources									
27. Justification for Emergency (If Block 15 is "Emergency"):									
28. Site(s) Affected: ☐ EDF ☐ PVC ☐ VATC ☐ EDC ☐ GSFC ☐ LaRC ☐ NSIDC ☐ SMC ☐ AK ☐ JPL ☐ EOC ☐ IDG Test Cell ☐ Other									
29. Board Comments:				30. V	ork Assigned To	o:	31. CCR C	Closed Date:	
32. EDF/SCDV CCB Chair (S	ign/Date): [-	pproved d/ECS	App/Cor	m. Disapproved	Wit	hdraw Fwd	/ESDIS ERB	
22 M20 CCD Chair (Cia/C	loto).			Ann/C===	Diconnected 1	۱۸/:۶۱	hdrow FI	/EQDIC EDD	
33. M&O CCB Chair (Sign/D Gary Gavigan /s/ 01/0	•	Disposition: Ap Fw	d/ECS	~hh/Coll	n. Disapproved	vvill	iiuiaw FWU/	LODIO END	
34. ECS CCB Chair (Sign/Da	ate): Di	isposition: Ap		App/Com	. Disapproved	Wit	hdraw Fwd	/ESDIS ERB	

CM01JA00 Revised 10/15/01 ECS/EDF/SCDV/M&O

Fwd/ESDIS